

Additional Monitoring Data			2020		Pekara
Compound	Results	Units	MCL	Sample Date*	Possible Source of Contaminant
<b>Inorganics</b>					
Arsenic	<1.0	µg/L	10	3.30.20	Erosion from natural deposits
Calcium	83.2	mg/L	n/a	4.1.20	Erosion from limestone or calcium containing rocks
Sodium	100.6	mg/L	n/a	4.1.20	Road salt, water softeners
Sulfate	414.0	mg/L	250	3.30.20	Erosion from soils and rock containing sulfates
Alkalinity	146.0	mg/L	n/a	3.17.20	Calcium carbonate, erosion from limestone or soils with dolomite and calcite
Chloride	27.1	mg/L	250	3.30.20	Road salt, water softeners, naturally occurring
Fluoride	1.59	mg/L	4	3.20.20	Erosion from natural deposits, added in the water treatment process
Total Hardness	420.8	mg/L	n/a	3.20.20	Corrosion of water pipes
Iron	<0.07	mg/L	0.3	3.20.20	Corrosion of iron pipes and iron baring soils
Manganese	<0.03	mg/L	0.05	3.20.20	Natural element in soils
pH	7.7	S.U.	6.5-8.5	3.16.20	Corrosion of water pipes
Zinc	0.037	mg/L	5	3.10.20	Galvanized surfaces, erosion of natural resources
<b>Organics</b>					
Vinyl Chloride	<0.5	µg/L	0.5	8.19.14	PVC piping, discharge from plastic factories
1,1 Dichloroethene	<0.5	µg/L	0.5	8.19.14	Industrial discharge from chemical and plastic factories
Methylene chloride	<0.5	µg/L	0.5	8.19.14	Industrial solvent, paint stripper
MTBE	<0.5	µg/L	0.5		Leaking underground storage tanks, was used as a fuel additive
trans-1,2-Dichloroethene	<0.5	µg/L	0.5	12.16.14	Industrial discharge from chemical and plastic factories
cis-1,2-Dichloroethene	<0.5	µg/L	0.5	8.19.14	Discharge from industrial chemical factories
1,1,1-Trichloroethane	<0.5	µg/L	0.5	8.19.14	Discharge from metal degreasing sites and other factories
Carbon tetrachloride	<0.5	µg/L	0.5	8.19.14	Discharge from chemical plants and other industrial activities
Benzene	<0.5	µg/L	0.5	8.19.14	Discharge from factories; leaching from gas storage tanks and landfills
1,2-Dichloroethane	<0.5	µg/L	0.5	8.19.14	Discharge from industrial chemical factories
Trichloroethene	<0.5	µg/L	0.5	12.16.14	Discharge from industrial chemical factories
1,2-Dichloropropane	<0.5	µg/L	0.5	12.16.14	Discharge from industrial chemical factories
Toluene	<0.5	µg/L	0.5	12.16.14	Discharge from petroleum factories
Tetrachloroethene	<0.5	µg/L	0.5	12.16.14	Discharge from factories, dry cleaners

Additional Monitoring Data		2020			Pekara
Compound	Results	Units	MCL	Sample Date*	Possible Source of Contaminant
<b>Organics</b>					
Tetrachloroethene	<0.5	µg/L	0.5	12.16.14	Discharge from factories, dry cleaners
1,1,2-Trichloroethane	<0.5	µg/L	0.5	12.16.14	Discharge from industrial chemical factories
Chlorobenzene	<0.5	µg/L	0.5	12.16.14	Discharge from chemical and agricultural chemical factories
Ethylbenzene	<0.5	µg/L	0.5	12.16.14	Discharge from petroleum refineries
Xylenes	<0.5	µg/L	0.5	12.16.14	Discharge from petroleum refineries and chemical factories
<b>Unregulated Contaminants</b>					
PFOA	<2.0	ng/L	2.0	12.2.19	Manmade chemical to make Teflon
PFOS	<2.0	ng/L	2.0	12.2.19	Fabric protector, manmade fluorosurfactant and global pollutant

mg/L - Parts per Million

µg/L - Parts per Billion

Ng/L - Parts per Trillion